

Further Analysis / Information


Photo



Description

Fretting seen on NDE bearing housing (oversize on inspection)


Photo



Description

Bearing temperature plateau reached after 36 minutes operation 50.5 Degrees C

Photo



Description

